







Product Instructions


PEX Press Connection




















- 1. Square off tubing to proper length. Uneven, jagged or irregular cuts will produce unsatisfactory connections.
- 2. If using FostaPEX tubing, insert into prep tool, push and turn until no more resistance is felt. If using ViegaPEX, continue to step 3.
- 3. Slide press sleeve fully over end of tubing.
- 4. Insert press fitting into tubing and engage fully.
- 5. Check full tubing insertion at view hole of sleeve.
- 6. Position press tool perpendicular over press sleeve and close tool jaws to engage ratchet.
- 7. Close handles, utilizing trigger to reduce grip span if desired.
- 8. Extend handle and continue ratcheting until automatic tool release occurs at proper compression force.
- Warning: The connection is not leakproof when the tool has been opened by emergency release.

